Approved For Release 2003/11/06: CIA-RDP84-00933R090500100008-0

25X1

ODP-81-1217 SAF-E624-81

MEMORANDUM FOR: Chief, Headquarters Engineering Branch/RECD/OL

25X1

FROM

Director, Consolidated SAFE Project Office/ODP

SUBJECT

: 400 Hz UPS for Project SAFE

REFERENCE

: Your Memo for D/CSPO/ODP, dated 4 Sept 1981,

Subject: 400 Hz UPS for Project SAFE

- 1. It is requested that you accept Emerson Electric's offer \$102,594 to buy back the electronics of the 400 HZ UPS ordered for Project SAFE.
- We have been unsuccessful in our pursuit of a more advantageous price. Apparently we will have to absorb as a loss the cost (\$35,000) of the associated batteries.
- 3. It is requested that another quarterly review of Project SAFE's renovation activities and cost be scheduled. Please call me on extension to establish the time.

25X1

Distribution:

Orig & 1 - Addressee

1 - ODP Registry

1 - SPS Chrono

Approved For Release 2003/11/06 : CIA-RDP84-00933R00050010000847 /

ATOTOOP SING W

16 September 1981

| | MEMORANDUM FOR THE RECORD | |
|------|--|----------|
| 25X1 | FROM : Chief, Systems Analysis Staff | |
| | SUBJECT: Installation of SAFE Terminals in Building | 25X1 |
| | REFERENCES: (a) Memo dtd 25 June 81 to DD/NFAC fr D/OCR subj. Allocation of SAFE Terminals in Block 1 | , |
| | (b) Memo dtd 4 Sept 81 to D/CSPO fr C/SAS subj. Initial Impact of NFAC Reorganization on SAFE | |
| 25X1 | 1. Per telecon between DC/SAS and Acting D/ODP, on 15 September 1981, the problem with installing SAFE | 25X1 |
| 25X1 | terminals is a near term problem, 8 to 10 weeks, and should not affect the installation of SAFE terminals in that building during the Block 1 time period. SAS, therefore, is planning to maintain the two thread concept recommended in (a) referenced memorandum and will proceed accordingly. | |
| | 2. The SAFE (b) referenced memorandum regarding the requirement for the installation of 29 SAFE terminals during Block 1 still applies. | 25X1 |
| | | 25X1 |
| | Attachments: As stated | |
| 25X1 | cc: | |